

PART/FULL CIRCLE ROTOR



FALCON 6504 ROTOR All Models



Ref. No. : 440

Date : 02/2003

Page: 1 of 1



Ref.	Part Description	Qty.	F-4-FC	F-4-PC
* INTERNAL ASSEMBLY				
1	Radius Adjustment Screw	1	208751	208751
2	Filter Screen W/SAM Check Valve	1	209702	209702
3 NOZZLES				
		See current whole goods price list.		
4	Third Port Nozzle	1	231777	231777
ACCESSORIES				
**	Support Tool	1	209226	209226
**	Lifter Tool	1	209227	209227

* DUE TO THE WAY THE FALCON IS ASSEMBLED AT THE PLANT, THE INTERNAL ASSEMBLY IS NOT AVAILABLE AS A REPLACEMENT PART. TO REPLACE A FALCON INTERNAL THAT IS ALREADY INSTALLED IN THE GROUND, WE SUGGEST THAT YOU REPLACE IT WITH THE INTERNAL OF A NEW FALCON.
**CONSULT TOOL SECTION IN CURRENT WHOLE GOODS PRICE LIST.